



**US Army Corps  
of Engineers®**

DETROIT DISTRICT

ATTN: CELRE-DE  
477 MICHIGAN AVENUE  
DETROIT MI 48226-2575  
HTTP://WWW.LRE.USACE.ARMY.MIL/

DATE: 11/25/2015

POC: Technical Services  
Branch  
(313)226-2384

**NOTICE TO NAVIGATION INTERESTS**

NOTICE NUMBER: 5568-1

LOCAL NUMBER: L15-09  
WATERWAY: ST. MARYS RIVER

EFFECTIVE: 11/30/2015 00:01 thru Until Further  
Notice EST

---

**ICE CONTROL BOOMS, COURSE 2, LITTLE RAPIDS CHANNEL**  
**ST. MARYS RIVER**

1. Installation of the Ice Control Booms at the head of Course 2, Little Rapids Channel will begin on or around 30 November 2015. The scheduled completion date for the ice booms will be on or before 11 December 2015.
2. The westerly portion Ice Control Boom projects into the channel no more than 40 feet immediately upstream of Light 99, (LLNR-14110), (F.G.). Submerged anchor chains and cables extend upstream from the floating portion of the boom to the ice stabilization island.
3. On the Easterly side of Little Rapids Cut Temporary Lighted Ice Buoy, R98B, (LLNR-14105), showing characteristic Quick Flashing Red, (Q.R.) will be installed in approximate position, 134 degrees true, 4,800 feet from Bayfield Dike Light, (LLNR-14185), (Iso.R.), to mark the upstream limits of the East Boom Anchor System. When Buoy R98B is positioned, the easterly 175 feet of the channel will be closed to navigation.
4. After the Ice Control Booms are installed the available channel width for navigation will be restricted to about 385 feet until removal of the booms in the spring of 2016. The positions of the booms to be installed are shown on the attached chartlet.
5. Vessel masters are cautioned that anchor chains and cables are located under water and extend upstream and shoreward of the visible portions of the booms. Mariners are requested to exercise care in navigating this area and to be especially alert to avoid fouling with the submerged chains and cables. Small boat operators are cautioned to stay clear of the steel piles, ice stabilization islands and partially submerged anchor cables, and to be especially alert after dark to avoid the floating portions of the ice booms.
6. Our internet address is: <http://www.lre.usace.army.mil/Missions/Operations.aspx>
7. Questions regarding this notice may be directed to our Technical Services Branch at (313) 226-2384.

//signed//

David L Wright  
Chief, Operations Office  
USACE - Detroit

